

# KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: FUEL SPILL

DATE OCCURRED 10-15-92

DATE REPORTED \_\_\_\_\_

TIME OCCURRED 0925

TIME REPORTED \_\_\_\_\_

LOCATION(S) OF OCCURRENCE:

SEE BELOW

REPORTED BY:

PHONE NO(S):

TOWER

SUMMARY:

TOWER REPORTED FUEL DRIPPED FROM WING TANK OF BAC 111 (SONICS AIRCRAFT) DURING TAXI FROM GATE 4 TO B-7. (SEE REPORT THIS DATE BY OFFICER DOUGLAS). I CHECKED THE TAXI ROUTE OF THE BAC 111 AND FOUND FUEL ON THE TAXIWAY IN PLACES. AMOUNT OF FUEL WAS NOT MAJOR--EXCEPT ON WEST TAXIWAY AT B-6. I CONTACTED GALVINS TO ASSIST AND WAS CONTACTED BY THEIR LINE MGR--LINE MANAGER (MORSE) OFFERED TO HELP WITH B-6--BUT HE FELT IT WAS PROBABLY NOT THEIR RESPONSIBILITY. I INFORMED MORSE I WOULD WASH DOWN THE SPILL. FD2 WAS USED, ALONG WITH CEJAR AND ABOUT 200 GALS OF WATER.

UP  
 CLD  
 CO  
 LGP  
 112  
 CDS  
 JRV  
 JW  
 FILED  
 BY  
 W

OFFICERS:

ACTION: